Ω Metrohm

Metrohm AG
CH-9101 Herisau
Switzerland
Phone +41 71 353 85 85
Fax +41 71 353 89 01
info@metrohm.com
www.metrohm.com

MagIC Net 2.2 Patch 1

Release Notes

1   Purpose

This document describes the differences between the new software version **MagIC Net 2.2 Patch 1** and its predecessor MagIC Net 2.2.

2   Fixed bugs and problems

- Fixed: In rare cases, gradient profiles were not processed correctly.
- Fixed: The column heater of the 881 Compact IC pro heated up to the maximum after a temperature below the current column heater temperature was set.

3   Compliance

The current software version does not contain any modifications regarding 21 CFR Part 11 and GAMP.

Herisau, 16 Feb 2011

D. Strohm

Vice President, Head of R&D