917 Coulometer



Metrohm AG lonenstrasse CH-9100 Herisau Switzerland Phone +41 71 353 85 85 Fax +41 71 353 89 01 info@metrohm.com www.metrohm.com **Release Notes**Firmware version 5.917.0022
2020-01-31
8.917.8008EN

1 Purpose

This document describes the changes, improvements and fixed bugs and problems in the following firmware version:

5.917.0022

in comparison with the firmware version:

5.917.0021

2 New functions

None

3 Improvements

The following improvements were made:

 Changes to date, time and time zone are documented in the Audit Trail.

4 Fixed bugs and problems

The following bugs and problems were fixed:

- The user interface froze after printing out the login options report and then starting a method.
- If a message was present on the user interface during automatic user logout, the system remained stuck in the login dialog.
- If the login dialog was confirmed quickly during instrument start-up, the system could remain stuck in the user login without password.
- It was possible to start a method from the «Change password» dialog, even if no user was logged in.

5 Known bugs and problems

None

6 Conformity

This firmware version does not contain any changes which affect the conformity of the product with regards to 21 CFR Part 11 and GAMP.

2 -----