

## Equipment for determination of temperature correction with Rancimats and PVC Thermomats.

6.5616.100

Set for exact temperature adjustment

Below, the accessories are grouped into Scope of delivery and Optional accessories. Please keep this printout at hand for ordering replacement material. These lists may be subject to change.

Scope of delivery 6.5616.100

Qt. Order no. Description



Pt100 temperature sensor (length 17.5 cm) with fixed cable and mini-DIN-plug. This glass-free temperature sensor is well suited for use with a 711 Liquino and instruments for stability measurement (743 Rancimat, 763 PVC Thermomat, 892 Professional Rancimat, or 895 Professional PVC Thermomat).



2 PCS

6.2042.040

Clamp for temperature sensor

Holding clamp for Pt100 temperature sensor for stability measuring instruments



1 PCS

6.2326.000

Silicone oil for stability measuring instruments (50 mL)

Silicone oil for the determination of temperature correction in stability measuring instruments



1 PCS

6.2418.000

Air tube for oil measurements

Set of 12 pieces. In combination with 6.1429.040.

