



Connection Box ICP-MS

6.2149.310

Metrohm IC (Remote Box MSB) MassHunter 5.3 Agilent ICP-MS

Order no.

6.2141.410 Remote cable, IC - Agilent ICP-MS

Connecting cable for synchronization of Metrohm IC Systems (930 IC Flex and 940 Professional IC) and Agilent ICP-MS systems



6.2141.420

Connecting cable, Remote Box MSB

Connecting cable between connection box and Remote Box MSB



6.2141.430

Connecting cable, leak sensor

Connecting cable between connection box and leak sensor inlet of the IC

